

## Dual Mass Fly Wheel Replacement Kit

### Product

The SBS Dual Mass Fly Wheel Replacement Kit is developed to reduce the repair costs on dual mass flywheel clutches. It includes a solid flywheel combined with a traditional clutch kit and fitting bolts.

### Advantages

- Significant clutch repair cost reduction
- Less wear due to more simple construction
- High operation reliability

### Range

The SBS range includes reference numbers for the most popular car models featuring this construction principle, and is under current development. For catalogue extract see opposite page. For full catalogue data on SBS Dual Fly Wheel Replacement Kit, please consult TecDoc or contact us.



### SBS

Scandinavian Brake Systems A/S develops, manufactures and distributes brake parts and other wear parts for cars, motorcycles and special applications where extensive brake and friction knowhow is required.



### Scandinavian Brake Systems A/S

Kuopiovej 11  
DK - 5700 Svendborg  
Tlf: +45 6321 1515  
Fax: +45 6321 1595  
sbs@sbs.dk  
www.sbs.dk





the **power**  
to stop you

Dual Mass Fly Wheel Replacement Kit

Ref.	Make	Model	Type	From
131952	CITROËN	C5	2.0 HDi	2001-
131952	CITROËN	C8	2.0 HDi	2002-
131952	CITROËN	EVASION	2.0 HDi	1999-
131952	CITROËN	JUMPY	2.0 Hdi	2000-
131952	FIAT	SCUDO	2.0 JTD	1999-
131952	FIAT	ULYSSE	2.0 JTD	1999-
131952	PEUGEOT	406	2.0 HDi	1998-
131952	PEUGEOT	607	2.0 HDi	2000-
131952	PEUGEOT	807	2.0 HDi	2002-
131952	PEUGEOT	EXPERT	2.0 HDi	2000-
1325100	FORD	MONDEO III	2.0 16V TDDi / TDCi	2000-
132596	FORD	GALAXY	1.9 TDI	1997-
132596	SEAT	ALHAMBRA	1.9 TDI	1996-
132596	VOLKSWAGEN	SHARAN	1.9 TDI	1996-
132597	FORD	TRANSIT	2.4 DI	2000-
132598	FORD	MONDEO III	2.0 16V TDDi / TDCi	2000-
132599	FORD	FOCUS	1.8 TDCi	2001-
132599	FORD	TRANSIT CONNECT	1.8 TDCi	2002-
133360	MERCEDES-BENZ	C-CLASS	C 320 (203.064)	2000-
133360	MERCEDES-BENZ	SPRINTER 2-t	208 CDI	2000-
133360	MERCEDES-BENZ	SPRINTER 3-t	308 CDI	2000-
133360	MERCEDES-BENZ	SPRINTER 4-t	408 CDI	2000-
133360	MERCEDES-BENZ	V-CLASS	V 200 CDI (638.294)	1999-
133360	MERCEDES-BENZ	VITO	108 CDI 2.2 (638.094)	1999-
133684	OPEL	COMBO	1.3 CDTI 16V	2005-
133684	OPEL	CORSA C	1.3 CDTI 16V	2005-
134575	TOYOTA	AVENSIS	2.0 D-4D	1999-
1347134	AUDI	A3	1.9 TDI	1996-
1347134	SEAT	CORDOBA	1.9 TDI	1997-
1347134	SEAT	IBIZA II	1.9 TDI	1997-
1347134	SEAT	IBIZA III	1.9 TDI	1999-
1347134	SEAT	LEON	1.9 TDI	1999-
1347134	SEAT	TOLEDO I	1.9 TDI	1996-
1347134	SEAT	TOLEDO II	1.9 TDI	1999-
1347134	SKODA	OCTAVIA	1.9 TDI	1996-
1347134	VOLKSWAGEN	BORA	1.9 TDI	1998-
1347134	VOLKSWAGEN	GOLF III	1.9 TDI	1996-
1347134	VOLKSWAGEN	GOLF IV	1.9 TDI	1997-
1347134	VOLKSWAGEN	NEW BEETLE	1.9 TDI	2001-
1347134	VOLKSWAGEN	PASSAT	1.9 TDI	1996-
1347134	VOLKSWAGEN	POLO CLASSIC	1.9 TDI	1996-
1347134	VOLKSWAGEN	POLO Variant	1.9 TDI	1998-
1347134	VOLKSWAGEN	VENTO	1.9 TDI	1996-
1347135	AUDI	A3	1.9 TDI	2003-
1347135	SEAT	ALTEA	1.9 TDI	2004-
1347135	SEAT	ALTEA XL	1.9 TDI	2006-
1347135	SKODA	OCTAVIA	1.9 TDI	2004-
1347135	SKODA	SUPERB	1.9 TDI	2008-
1347135	VOLKSWAGEN	CADDY III	1.9 TDI	2004-
1347135	VOLKSWAGEN	GOLF PLUS	1.9 TDI	2005-
1347135	VOLKSWAGEN	GOLF V	1.9 TDI	2003-
1347135	VOLKSWAGEN	GOLF VI	2.0 TDI	2008-
1347135	VOLKSWAGEN	JETTA III	1.9 TDI	2005-
1347135	VOLKSWAGEN	PASSAT	1.9 TDI	2005-
1347135	VOLKSWAGEN	TOURAN	1.9 TDI	2003-